

Training Session Plan

Unit of competency: Perform Circuit Connection		Unit Code : CONEIM1004A2	NTVQF Level -1	Session No - 01
Task: Perform two lamp control by series circuit with one SPST switch.				
Learning Outcomes: At the end of the session the learner will be able to Perform two lamp control by series circuit with one SPST switch according to industry standard with one hour.				
Relevant Performance Criteria: 1.1 Personal Protective Equipment (PPE) is collected and worn as per job requirement. 1.2 Workplace is prepared as per job requirement. 1.3 Tools, materials and drawing are collected as per job requirement. 2.1 Circuit materials are placed on the board. 2.2 Circuit accessories are fitted and connected using flexible wire as per drawing. 2.3 Circuit connection is checked according to the drawing. 2.4 Electrical circuit connection is checked using series lamp. 2.5 Series circuit is tested with connected power supply. 5.1 Work area is cleaned in accordance with workplace procedures. 5.2 Unused materials are stored for re-use or disposed following workplace procedures.				
Date : 15.03.2022 (Online Course) 16.04.2022 (Face to Face Course)		Trainer : Rasida Akter		
Session Duration : Online (1 hour) Face to Face (4 hour)				
Learning Segment And Approximate Time Required	Key Points & Activities # Greetings # Link to Previous Session: - What is married joint? - Where are used married joint? # Today's Outcome: Perform two lamp control by series circuit with one SPST switch. # Structure of The Session Discussion , Demonstration , Review and feedback # Stimulate Learners	Training Method Discussion Ice Breaking Presentation	Materials, Equipment's & Resources Internet Computer Presentation CBLM White Board White Board Marker	
Introduction 30 min				

Training Session Plan

Discussion and Demonstration 1 hour 30 min	- Social Status - Remuneration - Career Opportunity # Discussion • Series Circuit • Series Circuit feature • Materials • Fittings • Workplace clean and instruments re-stored. # Demonstration: (Do it normal, Do it slow , Do it together , Off you go) # During demonstration, make sure task is performed as per specification.	Demonstration Discussion Practical Session	CBLM Internet Computer presentation job sheet speciation sheet PPE Materials Fittings Measuring Instrument
Break 30 min			

Trainee practice 1 hour	# Observe the performance of the trainees and facilitate if required.	Practical Session	job sheet speciation sheet PPE Materials Fittings Measuring Instrument
Review and feedback 20 min	# Review: Summery of the session: Perform two lamp control by series circuit with one SPST switch. # Feedback to the learners: Questions & Answer, comments	Small Group Discussion. Practical Session	CBLM
Link to the next session 10 min	In the next session: Perform two lamp control by parallel circuit with two SPST switch.	Discussion	CBLM